










<https://www.youtube.com/watch?v=DbrDJWNAIUU>















# The Cause of the fire- Cleaning

- Cleaning of cold applied plastic (CAP) metal







# After the fire-

## Investigations conducted by:

- Police
-

# Police

- Dandenong CIB
- Liaised with CFA and Worksafe
- Outcome
  - Not Arson








# Worksafe- 2<sup>nd</sup> Phase

## Documents required

- Company information



# Worksafe Investigation outcomes

## - as September 2014

- Improvement notice issued
-

Class 3 Flammable storage container Approx  
\$11,000 (secondhand, refurbished)









# Worksafe- 3<sup>rd</sup> phase Investigation

- Individual interviews with all employees
- Frequent site visits- inspections and consultations
- Due to severity of incident, the case was referred to the prosecution team
- Case went to magistrates court and Image was charged with breaching the Dangerous Goods Act 1985








# Items lost











# Insurance – the legal jargon

Insured	Type of insurance		





Where to turn here?













